

TRIPLA

PT. APTI ADHI ANANTA

HAL I

VEHICLE INSPECTION



PT. APTI ADHI ANANTA

REPORT NO 001/W/BPN/2025 (No/Mechanic/Branch/Year)	DATE 09/Des/2025 (Day/Month/Year)	CLAIM NO 001/BPN/2025 (No/Branch/Year)	CLAIM DATE 09/Des/2025 (Day/Month/Year)
BRANCH BALIKPAPAN	MACHINE LOCATION TENGGARONG		MILEAGE 200
CUSTOMER NAME CV. BUMI ANUGERAH CAHAYA ABADI		CUSTOMER BUSINESS Contractor	
MACHINE MODEL HX60G	MACHINE SERIAL NO LSW060N3CS0036588	ATTACHMENT 1	ATTACHMENT 2
ENGINE MODEL Yanmar	ENGINE SERIAL NO K7360A	MODEL	MODEL
		MAKE	MAKE
		SERIAL NO	SERIAL NO
SMR/HRS 221,9	SMR/KMS 223	DELIVERY DATE 07/Sep/2025	TROUBLE DATE 09/Des/2025
			CORRECTED DATE 09/Des/2025

UNIT PICTURE

